

6E appears in dryer display (Temp control error) ambient too cool

Thermistor

Check for resistance (50-300K OHM) across thermistor

Replace thermistor

Wire harness

Check for the same resistive reading at the board

Replace wiring

Control board

Insert diagnostic board (38207) and perform diagnostic test.

Replace control board

Courtesy of Samurai Appliance Repair Man
For lots more help, surf on in to www.fixitnow.com.